




# AIR FACTORS

4771 ARROYO VISTA, SUITE D  
LIVERMORE, CA 94551

PH. # 925-579-0040  
FAX # 925-579-0044

## SUPPLY AIR CHAMBER Inlet Collar Damper



6-8-A